



Produkte
Products



Prüfbericht - Nr.: 11032874 001		Seite 1 von 2 Page 1 of 2			
<i>Test Report No.:</i>					
Auftraggeber: <i>Client:</i>	Yi Chi Hsiung Ind. Corp. No. 51, Lane 40, Beitang Rd. Homei Township, Changhua County, Taiwan				
Gegenstand der Prüfung: <i>Test item:</i>	Swing seat				
Bezeichnung: <i>Identification:</i>	P1017DWR	Serien-Nr.: <i>Serial No.:</i>	Engineering Samples		
Wareneingangs-Nr.: <i>Receipt No.:</i>	A000009765	Eingangsdatum: <i>Date of receipt:</i>	2013, Apr, 08		
Zustand des Prüfgegenstandes bei Anlieferung: <i>Condition of test item at delivery:</i>		Apparently Good			
Prüfort: <i>Testing location:</i>	TÜV Rheinland Taiwan Ltd., Taichung Branch Mechanical Laboratory No.9, Lane 36, Sec. 3, Minsheng Rd., Daya District, Taichung City 428, Taiwan, R.O.C.				
Prüfgrundlage: <i>Test specification:</i>	According to client's specification.				
Prüfergebnis: <i>Test Result:</i>	See test result				
Prüflaboratorium: <i>Testing Laboratory:</i>	TÜV Rheinland Taiwan Ltd., Taichung Branch Mechanical Laboratory No.9, Lane 36, Sec. 3, Minsheng Rd., Daya District, Taichung City 428, Taiwan, R.O.C.				
geprüft/ tested by:		kontrolliert/ reviewed by:			
<p>2013 Apr 12 </p> <p>Mac Kung / Engineer (TÜV Rheinland Taiwan Ltd.)</p>		<p>2013 Apr 12 </p> <p>Chih-Hao Lien / Manager (TÜV Rheinland Taiwan Ltd.)</p>			
Datum <i>Date</i>	Name/Stellung <i>Name/Position</i>	Unterschrift <i>Signature</i>	Datum <i>Date</i>	Name/Stellung <i>Name/Position</i>	Unterschrift <i>Signature</i>
Sonstiges/ Other Aspects:					
- Apply for test report service.					
Abkürzungen: P(ass) = entspricht Prüfgrundlage F(ail) = entspricht nicht Prüfgrundlage N/A = nicht anwendbar N/T = nicht getestet			Abbreviations: P(ass) = passed F(ail) = failed N/A = not applicable N/T = not tested		
<p>Dieser Prüfbericht bezieht sich nur auf das o.g. Prüfmuster und darf ohne Genehmigung der Prüfstelle nicht auszugsweise vervielfältigt werden. Dieser Bericht berechtigt nicht zur Verwendung eines Prüfzeichens.</p> <p><i>This test report relates to the a. m. test item. Without permission of the test center this test report is not permitted to be duplicated in extracts. This test report does not entitle to carry any safety mark on this or similar products.</i></p>					

Prüfbericht - Nr.: 11032874 001

Test Report No.:

Seite 2 von 2

Page 2 of 2

Clause	Requirement	Remarks	Verdict
1	Pulling test Check the breaking force for the sample.	By reaching force 6510 N (664 kg), the sample is strongly deformed and lose its function. The test setup and result please refer to picture 1 and 2.	--



Picture 1



Picture 2 (After test)

End of test report --